

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 1 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page, Item (56) References Cited, U.S. Patent Documents: insert the following omitted U.S. patents and publications in appropriate order:

--2003/0038150 A1	02/2003	Williams
5,316,192	05/1994	Ng
5,765,699	06/1998	Griffin
5,957,352	09/1999	Gares
6,626,339	09/2003	Gates et al.
6,641,014	11/2003	McNalley
2003/0168484 A1	09/2003	Gates et al.
2004/0020954 A1	02/2004	Gates et al.--

Title page, Item (56) References Cited, Other Publications: insert the following omitted publications in appropriate order:

--Rugged Gear Single Hook ATV Rack; <http://web.archive.org/web/20000613220655/http://www.ruggedgear.com>; January 8, 2005; 1 page.

Rugged Gear Double Hook ATV Rack;
<http://web.archive.org/web/20000616171814/www.ruggedgear.com/page28.htm>;
January 17, 2005; 1 page.

Rugged Gear ATV Rack — Double Hook; Part Information/Description sheet; Last Revised Date June 1, 1999; 1 page.

All Rite Products, Inc. illustration; circa 1986; 1 page.

All Rite Products, Inc. illustration; circa 1997; 1 page.

Rugged Gear Catalog (brochure from website); www.ruggedgear.com; January 2005; 7 pages.

Kolpin gun Grips II Mounting Instructions, May 17, 2005, 1 page.

Kolpin Gun Grips <http://atvs.ridegear.com>/page 1, May 18, 2005.--

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 2 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings, Sheet 1 of 6: Delete Drawings Sheet 1 of 6 and replace with the following drawing:




FIG. 1




FIG. 2




FIG. 3

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 3 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings, Sheet 2 of 6: Delete Drawings Sheet 2 of 6 and replace with the following drawing:




FIG. 4




FIG. 6

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 4 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings, Sheet 3 of 6: Delete Drawings Sheet 3 of 6 and replace with the following drawing:




FIG. 6


UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 5 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings, Sheet 4 of 6: Delete Drawings Sheet 4 of 6 and replace with the following drawing:





UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 6 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings, Sheet 5 of 6: Delete Drawings Sheet 5 of 6 and replace with the following drawing:




UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 7 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings, Sheet 6 of 6: Delete Drawings Sheet 6 of 6 and replace with the following drawing:



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,808 B2
APPLICATION NO. : 10/035290
DATED : September 5, 2006
INVENTOR(S) : Hancock et al.

Page 8 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 3, line 41: "has comer holes 74" should read --has corner holes 74--

Col. 3, line 52: "walls at comers" should read --walls at corners--

Col. 5, line 22, claim 1: "bottom with a" should read --bottom surface with a--

Signed and Sealed this

Tenth Day of July, 2007

A handwritten signature in black ink, appearing to read "Jon W. Dudas". The signature is stylized with a large, looped initial "J" and a distinct "D" at the end.

JON W. DUDAS
Director of the United States Patent and Trademark Office